



REPAIR COST ESTIMATE

K1E456

| | | |
|---|------------------------|--|
| LOCATION OF DAMAGE PROPERTY: SR 005 Begin MP: 207.80 Dir: Southbound Southbound I-5, MP 207.8 | COUNTY 31 Snohomish | DAMAGE CODE 31 Guardrail, Leading End |
|---|------------------------|--|

| | |
|--|--|
| DATE DAMAGE OCCURRED OR OBSERVED: 12/12/2014 OBSERVED | DESCRIPTION OF DAMAGES Guardrail End damage plus damage to Sign |
|--|--|

| | |
|--|---|
| NAME AND ADDRESS OF OWNER: [REDACTED] | NAME AND ADDRESS OF DRIVER: [REDACTED] |
|--|---|

| | | | | |
|--|--------------------------|-------------|--|---------------|
| YEAR, MAKE, TYPE OF VEHICLE: 2002 Ford R10PU 4C | LICENSE: D [REDACTED] | DAMAGE TAG: | POLICE DIV: Washington State Patrol | BADGE: 310 |
|--|--------------------------|-------------|--|---------------|

REPAIR COST DISTRIBUTION ESTIMATE

| LABOR DESCRIPTION | QTY | REG. HOURS | O/T HOURS | AMOUNT |
|------------------------------|-----|------------|-----------|-------------------|
| Maintenance Lead Tech. | 1 | 10.0 | | \$494.70 |
| Maintenance Lead Tech. | 1 | 5.0 | | \$247.35 |
| Maintenance Tech. 2 | 2 | 10.0 | | \$807.82 |
| Maintenance Tech. 2 | 2 | 8.0 | | \$646.26 |
| Maintenance Tech. 3 | 1 | 8.0 | | \$350.11 |
| TOTAL LABOR ESTIMATE: | | | | \$2,546.24 |

| EQUIPMENT TYPE | QTY | HOURS | AMOUNT |
|--|-----|-------|-----------------|
| 0435 - Truck; 1 Ton; with Dump Body; Extended / Crew Cab; Diesel; with Tommy Lift or Crane | 1 | 8.0 | \$86.13 |
| 0505 - 1 Ton; Crew Cab; Gasoline; 4x2 | 1 | 5.0 | \$31.38 |
| 0507 - 1 Ton; Crew Cab; Diesel; 4x2 | 1 | 10.0 | \$75.46 |
| 0614 - Truck; Tandem Axle; 54,000 GVW and above; 6x4; Man Trans; w/ Double Dump Body; w/front plow | 1 | 8.0 | \$166.47 |
| 0820 - Truck; Flatbed; Traffic Control Items; Less Than 38,000 GVW (Road Warrior) | 2 | 9.0 | \$184.91 |
| 1207 - Backhoe; Excavator; Compact; Track Mounted; 10-12K Operating Weight | 1 | 8.0 | \$53.10 |
| TOTAL EQUIPMENT ESTIMATE: | | | \$597.44 |

| MATERIAL TYPE | QTY | AMOUNT |
|---|-----|-----------------|
| Guard Rail - Wood Post, 6" x 8" x 3'6" | 2 | \$45.43 |
| Guard Rail, Beam, Punched Type 31 | 2 | \$289.05 |
| Guard Rail, W beam SKT 350 end 15' x 7'1/2" | 1 | \$276.34 |
| TOTAL MATERIAL ESTIMATE: | | \$610.82 |



REPAIR COST ESTIMATE

K1E456

| | | |
|---|------------------------|--|
| LOCATION OF DAMAGE PROPERTY: SR 005 Begin MP: 207.80 Dir: Southbound Southbound I-5, MP 207.8 | COUNTY 31 Snohomish | DAMAGE CODE 31 Guardrail, Leading End |
|---|------------------------|--|

| MISCELLANEOUS CHARGES - DESCRIPTION | QTY | AMOUNT |
|--------------------------------------|-----|---------------|
| | | \$0.00 |
| TOTAL MISCELLANEOUS ESTIMATE: | | \$0.00 |

TOTAL CHARGES: \$3,754.50

| | | | |
|---|---------------------|---|-------------------|
| MAINT. AREA LOCATION: Area 2 Mt Vernon | ORG CODE: 415220 | CONT. SECTION A22005 | JOB NO: K1E456 |
| SUBMITTED BY: Al Hendrickson | DATE: 12/31/2014 | | |
| APPROVED BY: Kim Glass | DATE: 01/05/2015 | OFFICE USE ONLY: Estimate Only: Y Accident Rpt: E384955 Revised Estimate: N Work Completed: Y Work Completed Date: 12/22/2014 | |











