



## REPAIR COST ESTIMATE

K1B518

LOCATION OF DAMAGE PROPERTY: SR 005 Begin MP: 208.70 Dir: Southbound I-5 and SR 530 under the over pass	COUNTY 31 Snohomish	DAMAGE CODE 31 Guardrail, Leading End
--	------------------------	--

DATE DAMAGE OCCURRED OR OBSERVED: 12/05/2012 OCCURRED	DESCRIPTION OF DAMAGES GR Leading end and Traffic Control
--	--

NAME AND ADDRESS OF OWNER: [REDACTED]	NAME AND ADDRESS OF DRIVER: [REDACTED]
--	---

YEAR, MAKE, TYPE OF VEHICLE: 2007 GMC	LICENSE: [REDACTED]	DAMAGE TAG: [REDACTED]	POLICE Washington State Patrol	[REDACTED] WSP 332
--	------------------------	---------------------------	-----------------------------------	-----------------------

### REPAIR COST DISTRIBUTION ESTIMATE

LABOR DESCRIPTION	QTY	REG. HOURS	O/T HOURS	AMOUNT
Maintenance Lead Tech.	1	16.0		\$766.12
Maintenance Lead Tech.	1	4.0	1.0	\$252.34
Maintenance Supervisor	1	4.5		\$234.01
Maintenance Tech. 2	2	16.0		\$1,253.23
Maintenance Tech. 2	2	20.5		\$1,605.69
<b>TOTAL LABOR ESTIMATE:</b>				<b>\$4,111.39</b>

EQUIPMENT TYPE	QTY	HOURS	AMOUNT
0305 - Truck; Pickup; Incident Response (IRL); Diesel	1	5.0	\$68.97
0433 - Truck; 1 Ton; with Dump Body; Extended / Crew Cab; Diesel	1	16.0	\$117.29
0507 - 1 Ton; Crew Cab; Diesel; 4x2	1	16.0	\$136.84
0520 - 1/2 Ton; Extended Cab; 4x4	1	4.5	\$23.74
0614 - Truck; Tandem Axle; 54,000 GVW and above; 6x4; Man Trans; w/ Double Dump Body; w/front plow	1	16.0	\$326.46
0820 - Truck; Flatbed; Traffic Control Items; Less Than 38,000 GVW (Road Warrior)	1	20.5	\$213.12
1005 - Tilt / Flatbed Trailer; 50,000 Lbs.	1	16.0	\$29.50
1207 - Backhoe; Excavator; Compact; Track Mounted; 10-12K Operating Weight	1	16.0	\$100.94
<b>TOTAL EQUIPMENT ESTIMATE:</b>			<b>\$1,016.86</b>



## REPAIR COST ESTIMATE

K1B518

LOCATION OF DAMAGE PROPERTY: SR 005 Begin MP: 208.70 Dir: Southbound I-5 and SR 530 under the over pass	COUNTY 31 Snohomish	DAMAGE CODE 31 Guardrail, Leading End
---	------------------------	--

MATERIAL TYPE	QTY	AMOUNT
Gr Block 4 x 12 x 14" Poly Block	8	\$139.77
Gr Et 2000 Panel #1 15'7" Type 31 20442g Galvanized	1	\$194.72
Gr Post 6" X 9" X 6' Steel	8	\$521.94
Guard Rail - Wood Block, Spacer 6x12x14"	8	\$117.56
Guard Rail - Wood Post, 6" x 8" x 4.25'	3	\$110.79
Guard Rail ET2000 Panel 1, SYRO	1	\$171.66
Guard Rail, Beam, Punched Type 31	4	\$536.47
Guard Rail, Beam, Punched Type 31	2	\$268.23
Guard Rail, Post, 6" x 8" x 6', CRT. 2-Hole	8	\$324.06
Guard Rail, Terminal End "C" Galvanized	1	\$43.04
<b>TOTAL MATERIAL ESTIMATE:</b>		<b>\$2,428.23</b>

MISCELLANEOUS CHARGES - DESCRIPTION	QTY	AMOUNT
		\$0.00
<b>TOTAL MISCELLANEOUS ESTIMATE:</b>		<b>\$0.00</b>

**TOTAL CHARGES: \$7,556.49**

MAINT. AREA LOCATION: Area 2 Mt Vernon	ORG CODE: 415220	CONT. SECTION A22005	JOB NO: K1B518
SUBMITTED BY: John Tate	DATE: 12/13/2012		
APPROVED BY: Gary Ward	DATE: 12/13/2012	OFFICE USE ONLY: Estimate Only: N Accident Rpt: 3467933 Revised Estimate: N Work Completed: Y Work Completed Date: 12/10/2012	



 **InterUrban**  
Delivery Service Ltd.  
*The People's Choice for the Delivery Industry*  
604-852-8998

**CAUTION**  
PUSH BACKWARDS  
ON RAMPAGE  
CONTROL THE SPEED

3

530  
115

99-3750








604-852-8998

835347

**InterUrban**  
Delivery Services  
1-888-258-0722

**GMC**



 **InterUrban**

Neighborhood  
Service Ltd.

*Delivering Excellence*

1-800-451-1111

 **InterUrban**  
1-800-451-1111  
Delivering Excellence





MARYSVILLE *Dick's* EVERETT

80 TON ROTATOR

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban

InterUrban









Previous Next

Record X of X

[Email This Record](#)

<b>Record Number:</b> 225560	<b>Submitted By:</b> Dennis Rudig Radio #: 1830	<b>Domain Account:</b> WSDOT\RudigM	<b>Unit Type:</b> Roving IR		
<b>Start Date:</b> 12/5/2012	<b>Notification Time:</b> 10:09	<b>Notified By:</b> Roved Upon	<b>Arrival Time:</b> 10:09	<b>All Lanes Open:</b> 13:40	<b>Time Scene Cleared:</b> 13:55
<b>State Route:</b> 005		<b>Action(s) Taken:</b>			
<b>Direction:</b> SB		Advised WSP			
<b>Mile Post:</b> 208.00		Remove Debris			
<b>Landmark:</b> SR530 BRIDGE 115		Traffic Control			
<b>Maintenance Area:</b>					
<b>Incident Type:</b> Collision-Non-Injury					
<b>Lane Closures</b>					
<b>Primary Direction:</b> Single Lane			<b>Secondary Direction:</b>		
<b>Involved Vehicles:</b> BC P93750 : Heavy		<b>Other Responders:</b>		<input type="checkbox"/> Fire <input checked="" type="checkbox"/> WSDOT Property Damage <input type="checkbox"/> Hazardous Material <input type="checkbox"/> Work Zone <input type="checkbox"/> Comment Card Provided	
Total Number of Vehicles: 1		WSP, 332 WSP, 876 WSP, 651 WSP, 155 WSP, X844 Fire/Rescue, SILVANA WSDOT Maint, 125 WSDOT Maint, 121 WSDOT Maint, 1256 WSDOT Maint, 1252 WSDOT Maint, 1254			
<b>CAD Number:</b>	<b>SitStat Number:</b> Not Available	<b>WSP Collision Report Number:</b> 3467933			
<b>Comments:</b>					
BEAM GUARDRAIL DAMAGE TOOK LANE 1 FOR TOW 1114 TO 1340 APPROXIMATELY 60 FEET OF BEAM RAIL AND POSTS.					

Previous Next

View or Add Images

Edit Supplement





530  
115

**CAUTION**  
IF YOU CAN'T SEE  
MY MIRRORS  
I CAN'T SEE YOU  
THIS TRUCK MAKES WIDE  
RIGHT HAND TURNS

3

**IB** INTERCONTINENTAL  
TRUCK RENTAL  
RENTAL & SALES CORPORATION



NEW YORK  
P9-3750  
NEW YORK





















