#### Washington State Department of Transportation

## **REPAIR COST ESTIMATE**

						K1B848			
LOCATION OF DAMAGE PROPERTY:		COUNTY			DAMAGE CODE				
SR 018 Begin MP: 0.27 Dir: Westbound Southb SR 167 ramp to Westbound SR 18, right side. Ramp 018 S1 00227-INC		17 King			31 Guardrail, Leading End				
DATE DAMAGE OCCURRED OR OBSERVED:	DES	DESCRIPTION OF DAMAGES							
02/28/2013 OBSERVED	) ET 2	ET 2000							
NAME AND ADDRESS OF OWNER:	NAM	NAME AND ADDRESS OF DRIVER:							
Same Same									
YEAR, MAKE, TYPE OF VEHICLE: LICENSE:	DAM	IAG	E TAG: POLICI		DIV:	BADGE:			
2007 HOND ACDD 6		V			ashington State Patrol 107				
REPAIR COST DISTRIBUTION ESTIMATE									
LABOR DESCRIPTION	QTY		REG. HOURS		O/T HOURS	AMOUNT			
Maintenance Lead Tech.	1				2.0	\$113.89			
Maintenance Lead Tech.	1		2.5			\$125.34			
Maintenance Tech. 1	1				2.0	\$89.63			
Maintenance Tech. 2	2				2.0	\$211.83			
Maintenance Tech. 3	1				2.0	\$105.92			
TOTAL LABOR ESTIMATE:						\$646.62			
EQUIPMENT TYPE			QTY		HOURS	AMOUNT			
0401 - Truck; 15,000 GVW; without plow (From sub	class 0601)		1		2.0	\$13.56			
0435 - Truck; 1 Ton; with Dump Body; Extended / C Diesel; with Tommy Lift or Crane	1		2.5	\$27.75					
0602 - Truck; Less than 38,000 GVW; with front plo	1		2.0	\$32.52					
0820 - Truck; Flatbed; Traffic Control Items; Less Th GVW (Road Warrior)	2		3.5	\$50.46					
0825 - Truck; Flatbed; Guardrail Repair; 54,000 GV Knuckle boom Crane	1		2.0	\$23.50					
2123 - Impact Attenuator (T	ed)	2		2.5	\$5.83				
2160 - Message Sign; Vehicle Mounted; 3 Line Mes		2		2.5	\$9.24				
2303 - Sander; Tailgate		1		2.0	\$0.91				
TOTAL EQUIPMENT ESTIMATE:						\$163.77			



## **REPAIR COST ESTIMATE**

				K1B848			
LOCATION OF DAMAGE PROPERTY:	DAN	DAMAGE CODE					
SR 018 Begin MP: 0.27 Dir: Westbour SR 167 ramp to Westbound SR 18, right 018 S1 00227-INC	31 Guard	31 Guardrail, Leading End					
MATERIAL TYPE			QTY	AMOUNT			
Gr ET 2000 Panel #1 13 Ft 6 1/2 In At 6	1	\$187.71					
Gr Post 5.5 Ln X 7.5 Ln X 3 Ft 9 Ln ET2	1	\$34.75					
GUARDRAIL, BOLT NUT WASHER 5/8	8	\$9.77					
GUARDRAIL, BOLT NUT WASHER 5/8	2	\$4.22					
TOTAL MATERIAL ESTIMATE:			•	\$236.46			
MISCELLANEOUS CHARGES - DESCRIPTION QTY AMOUNT							
		\$0.00					
TOTAL MISCELLANEOUS ESTIMATE				\$0.00			
TOTAL CHARGES:				\$1,046.85			
MAINT. AREA LOCATION:	ORG CODE:	CONT. SECTION	JOB NO:				
KELLEHP@wsdot.wa.gov	415420	A42018	K1B848				
SUBMITTED BY:	DATE:						
Chuck Edwards	10/01/2013						
APPROVED BY:	DATE:	OFFICE USE ONLY:					
Tom Wagner	10/01/2013	Estimate Only: Y Accident Rpt: E233976 Revised Estimate: N Work Completed: Y Work Completed Date: 03/13/2013					

E Banda TI 02.28.2013 15:21



.






ORIGINAL

# Stores Ticket (8420)

Date		Originating Location Tr					Transfer To Location (For Transfers Only)					Ticket Number		
3/10	13		Region	MA L	ICP	Region		MA	ICP	A104470		470		
Issue	1	Nork	(Order	Group	Org Code	Code Office / Vessel / Terminal								
Deturn		01	si cont l'	7.7										
Transfer KIB848 OI $415420$														
Equip. or Cont. Sec.	Function of Work Op	2 12	Commodity C	ode	Description				Unit	Quantity Ordered	Quantity Iss/Ret/Trans			
142167	3154	5	421-010-	.500 G	Gueard Rail, ET2000 Panel 1							1		
A42167	3154	5	421-052-7	120 P	Post, Guardrail Non Bandrad 6"x8" x 3'9"									
Requested By Authorized By														
		Re	disard	Rec	ceived By (Legit	ole Signature	e)		Receiving L	ocation				
DOT Form 72 Revised	25-015 EF 1 8/08													



#### GRASSY LEFT SHOULDER/GORE POINT