

REPAIR COST ESTIMATE

Department of Transporta			11		COSI L	SIIWAIL				
						K1C828				
LOCATION OF DAMAGE PROPERTY		COUNTY		DAM	DAMAGE CODE					
SR 005 Begin MP: 184.20 Dir: South Southbound M.P. 184.2 Off Ramp to 16 Shoulder.	31	Snohomi	sh	31 Guard	31 Guardrail, Leading End					
DATE DAMAGE OCCURRED OR OBS	DESCR	DESCRIPTION OF DAMAGES								
11/18/2013	OBSERVED	Guardra	Guardrail, Leading Edge							
NAME AND ADDRESS OF OWNER:	NAME A	NAME AND ADDRESS OF DRIVER:								
Same					_					
YEAR, MAKE, TYPE OF VEHICLE:	AR, MAKE, TYPE OF VEHICLE: LICENSE:				DIV:	BADGE:				
2010 Honda CRV			Snohomis			neriff 1363				
R	EPAIR COST	DISTRIBUT	ION ESTI	MATE		<u> </u>				
LABOR DESCRIPTION		QTY	REG. H	IOURS	O/T HOURS	S AMOUNT				
Maintenance Lead Tech.	laintenance Lead Tech.					\$103.38				
Maintenance Tech. 2	3	5.	0		\$633.08					
Maintenance Tech. 3	1	5.	0		\$228.65					
TOTAL LABOR ESTIMATE:						\$965.11				
EQUIPMENT TYPE			QTY	′	HOURS	AMOUNT				
0820 - Truck; Flatbed; Traffic Control It GVW (Road Warrior)	n 38,000	1	5.0		\$52.59					
0825 - Truck; Flatbed; Guardrail Repail Knuckle boom Crane	; 54,000 GVW;	with	1		5.0	\$52.59				
TOTAL EQUIPMENT ESTIMATE:						\$105.18				
MATERIAL TYPE					QTY	AMOUNT				
Block, Guard Rail Spacer 6x8x14" - Ea	3	\$21.42								
ET 2000 Panel #1	1	\$183.79								
ET 2000 Panel #115' 7" Type 31	1	\$199.95								
Post, Guard Rail 6"x8"x 3' 9"	2	\$84.84								
Post, Guard Rail, CRT	1	\$72.43								
TOTAL MATERIAL ESTIMATE:						\$562.43				

Page 1 DATE PRINTED: 1/28/2015



REPAIR COST ESTIMATE

Department of Irans	REPAIR COST ESTIMATE							
				K1C828				
LOCATION OF DAMAGE PROP	ERTY:	COUNTY	DAM	DAMAGE CODE				
SR 005 Begin MP: 184.20 Dir: Southbound M.P. 184.2 Off Ram Shoulder.		31 Snohomish	31 Guard	rail, Leading End				
MISCELLANEOUS CHARGES -	DESCRIPTION		QTY	AMOUNT				
				\$0.00				
TOTAL MISCELLANEOUS EST	IMATE:			\$0.00				
TOTAL CHARGES:				\$1,632.72				
MAINT. AREA LOCATION:	ORG CODE:	CONT. SECTION	JOB NO:					
Area 3 Everett	415310	A31005	K1C828					
SUBMITTED BY:	DATE:							
Tim Nash	11/26/2013							
APPROVED BY:	DATE:	OFFICE USE ONLY:						
John Tellesbo	11/26/2013	Estimate Only: Y A Revised Estimate: N Work Completed: Y Work Completed Date	ccident Rpt: E285 :: 11/26/2013	5711				

Page 2 DATE PRINTED: 1/28/2015







Stores Ticket (8420)

Date						Transfer To Location (For Transfers							
			Region	MA		ICP	Region	1	MA	ICP		C21	151
11/20	5/2013		001	03		030 A				l	G34451		
✓ Issue	☑ Issue Work Order Group			Org Code	Office / Vessel / Termin			Terminal					
	□ Return □ Transfer K1C828		0	415310 Everett Maintena			enance			1			
Equip. or Cont. Sec.	Function Work O		Commodity C	Code Description					Unit	Quantity Ordered	Quantity Iss/Ret/Trans		
A31005	3154		5407-341-2	GR POST TRINITY 6 IN X 8 IN X 6 FT CRT 2 HOLE PC 4063B SRT/ET SYSTEMS						T CRT 2	EA	1	1
A31005	3154		5702-849-5	521	GR ET 2000 PANEL NO 1 13 FT 6 1/2 IN AT 6 FT 3 IN 32G GALVANIZED					EA	1	1	
A31005	3154		5702-849-5	524	GR, ET 2000 Panel #2 15', 7" Type 31, 20442G Galvanized					EA	1	1	
A31005	3154		5407-341-1	75		GR POST 6 IN X 8 IN 3 FT 9 IN OR EQUAL TRINITY SRT350 6058B ET2000 4147B				EA	-1	1	
8													
Requested I	Ву						Author	ized	Ву	erminal E	Entry	11-26-1	3 MM
Tim Nas	sh												l
Issued By					Received By (Legible Signature)			Receiving I	eceiving Location				