



REPAIR COST ESTIMATE

K1E068

LOCATION OF DAMAGE PROPERTY: SR 526 Begin MP: 0.70 End MP: 0.70 Dir: Westbound SR-526 Westbound right side just West of the Boeing shipping and receiving traffic signal.	COUNTY 31 Snohomish	DAMAGE CODE 31 Guardrail, Leading End
--	------------------------	--

DATE DAMAGE OCCURRED OR OBSERVED: 09/17/2014 OBSERVED	DESCRIPTION OF DAMAGES SKT Guardrail system.
--	---

NAME AND ADDRESS OF OWNER: [REDACTED]	NAME AND ADDRESS OF DRIVER: [REDACTED]
--	---

YEAR, MAKE, TYPE OF VEHICLE: 2011 BMW M3	LICENSE: [REDACTED]	DAMAGE TAG:	POLICE DIV: Everett Police Department	BADGE: 1380
---	------------------------	-------------	--	----------------

REPAIR COST DISTRIBUTION ESTIMATE

LABOR DESCRIPTION	QTY	REG. HOURS	O/T HOURS	AMOUNT
Maintenance Lead Tech.	1	1.0	0.0	\$51.94
Maintenance Tech. 2	3	3.0	0.0	\$381.69
Maintenance Tech. 3	1	3.0	0.0	\$137.86
TOTAL LABOR ESTIMATE:				\$571.50

EQUIPMENT TYPE	QTY	HOURS	AMOUNT
0401 - Truck; 15,000 GVW; without plow (From subclass 0601)	1	1.0	\$8.76
0606 - Truck; Above 38,000 GVW; 4x2, Contractor Body; with front plow	1	3.0	\$34.89
0820 - Truck; Flatbed; Traffic Control Items; Less Than 38,000 GVW (Road Warrior)	1	3.0	\$30.82
0825 - Truck; Flatbed; Guardrail Repair; 54,000 GVW; with Knuckle boom Crane	1	3.0	\$30.49
TOTAL EQUIPMENT ESTIMATE:			\$104.96

MATERIAL TYPE	QTY	AMOUNT
Guard Rail, SKT 350, TL2/TL3	1	\$256.07
Post, Guard Rail 6"x8"x 3' 9"	1	\$43.05
TOTAL MATERIAL ESTIMATE:		\$299.12



REPAIR COST ESTIMATE

K1E068

LOCATION OF DAMAGE PROPERTY: SR 526 Begin MP: 0.70 End MP: 0.70 Dir: Westbound SR-526 Westbound right side just West of the Boeing shipping and receiving traffic signal.	COUNTY 31 Snohomish	DAMAGE CODE 31 Guardrail, Leading End
---	-------------------------------	---

MISCELLANEOUS CHARGES - DESCRIPTION	QTY	AMOUNT
		\$0.00
TOTAL MISCELLANEOUS ESTIMATE:		\$0.00

TOTAL CHARGES: \$975.58

MAINT. AREA LOCATION: Area 3 Everett	ORG CODE: 415340	CONT. SECTION A34526	JOB NO: K1E068
SUBMITTED BY: James Christo	DATE: 09/18/2014		
APPROVED BY: Ron Morton	DATE: 10/07/2014	OFFICE USE ONLY: Estimate Only: Y Accident Rpt: E356180 Revised Estimate: N Work Completed: Y Work Completed Date: 10/03/2014	





Date 10/7/2014		Originating Location Region MA ICP 001 03 030A		Transfer To Location (For Transfers Only) Region MA ICP		Ticket Number G38116	
<input checked="" type="checkbox"/> Issue <input type="checkbox"/> Return <input type="checkbox"/> Transfer		Work Order K1E068	Group 01	Org Code 415340 415300	Office / Vessel / Terminal NWR Everett Maintenance		
Equip. or Cont. Sec.	Function or Work Op	Commodity Code	Description	Unit	Quantity Ordered	Quantity Iss/Ret/Trans	
A34526	3154	5702-813-010	GR 13 FT 6 1/2 IN W BEAM ANCHOR FLEAT PUNCH PATTERN PANEL NO 1 END	EA		1	
A34526	3154	5407-341-175	GR POST 6 IN X 8 IN 3 FT 9 IN OR EQUAL TRINITY SRT350 6058B ET2000 4147B	EA		1	
Terminal Entry 10-7-14 <i>QMM</i>							
Requested By Todd Jones				Authorized By			
Issued By			Received By (Legible Signature) Eric Mills		Receiving Location		

45

10/07/2014