

REPAIR COST ESTIMATE

TELAN GOOT EOTHIAT						O 1 11117 (1 L	
						K1C144	
LOCATION OF DAMAGE PROPERTY:			COUNTY		DAMAGE CODE		
SR 005 Begin MP: 191.50 Dir: Southbound I-5 Southbound M.P. 191.5			31 Snohomish 31 Guardrail, L			rail, Leading End	
DATE DAMAGE OCCURRED OR OBSERVED:			DESCRIPTION OF DAMAGES				
05/20/2013 OBSERVED		Leadir	Leading Edge Guardrail				
NAME AND ADDRESS OF OWNER:			NAME AND ADDRESS OF DRIVER:				
YEAR, MAKE, TYPE OF VEHICLE:	LICENSE:	DAMA	DAMAGE TAG: POLICI		DIV:	BADGE:	
2009 Pontiac Grand	1		Washin		gton State Pat	rol 1090	
F	REPAIR COST	DISTRIBU	TION EST	MATE		•	
LABOR DESCRIPTION		QTY	REG. F	IOURS	O/T HOURS	AMOUN	
Maintenance Lead Tech.		1	1.	.0		\$50.2	
Maintenance Tech. 2		3	2.	.0		\$221.5	
Maintenance Tech. 3		1	2.	.0		\$88.9	
TOTAL LABOR ESTIMATE:						\$360.6	
EQUIPMENT TYPE			QT	<u> </u>	HOURS	AMOUN	
0825 - Truck; Flatbed; Guardrail Repair; 54,000 GVW; with Knuckle boom Crane			1		6.0	\$70.5	
TOTAL EQUIPMENT ESTIMATE:						\$70.5	
MATERIAL TYPE					QTY	AMOUNT	
ET 2000 Panel #1					1	\$162.2	
Post, Guard Rail 6"x8"x 3' 9"				2	\$68.2		
TOTAL MATERIAL ESTIMATE:						\$230.5	

Page 1 DATE PRINTED: 1/29/2015



REPAIR COST ESTIMATE

Department of Trans	REPAIR COST ESTIMATE					
				K1C144		
LOCATION OF DAMAGE PROPERTY:		COUNTY	COUNTY DAMAGE CODE			
SR 005 Begin MP: 191.50 Dir Southbound M.P. 191.5	31 Snohomish	31 Guard	31 Guardrail, Leading End			
MISCELLANEOUS CHARGES		QTY	AMOUNT			
				\$0.00		
TOTAL MISCELLANEOUS EST	IMATE:		•	\$0.00		
TOTAL CHARGES:				\$661.71		
MAINT. AREA LOCATION:	ORG CODE:	CONT. SECTION	JOB NO:			
Area 3 Everett	415310	A31005	K1C144			
SUBMITTED BY:	DATE:		•			
Tim Nash	04/30/2014					
APPROVED BY:	DATE:	OFFICE USE ONLY:				
Tom Wagner	04/30/2014	Estimate Only: Y Accident Rpt: E245161 Revised Estimate: N Work Completed: Y Work Completed Date: 05/22/2013				

Page 2 DATE PRINTED: 1/29/2015

