

REPAIR COST ESTIMATE

						K1C67		
LOCATION OF DAMAGE PROPERTY		COUNTY		DAMAGE CODE				
SR 018 Begin MP: 27.90 End MP: 2 Westbound I90 RIGHT SIDE		17 King		31 Guardrail, Leading End				
DATE DAMAGE OCCURRED OR OB	SERVED:	DESCR	IPTION C	F DAMA	AGES			
10/23/2013 OCCURRED		GUARE	GUARDRAIL LEADING END					
NAME AND ADDRESS OF OWNER:			NAME AND ADDRESS OF DRIVER:					
Unknown								
YEAR, MAKE, TYPE OF VEHICLE:	LICENSE:	DAMAG	SE TAG: POLICE		DIV:	BADGE:		
2008 Peterbuilt Tractor				Washin	gton State Patrol	1086		
ı	REPAIR COST	DISTRIBUT	ON ESTI	MATE		I		
LABOR DESCRIPTION		QTY	REG. H	OURS	O/T HOURS	AMOUN ⁻		
Maintenance Lead Tech.		1	3.	0		\$155.0		
Maintenance Lead Tech.		2			5.0	\$644.0		
Maintenance Tech. 2		1	3.0			\$132.6		
Maintenance Tech. 2		3			5.0	\$796.12		
Maintenance Tech. 3		1			5.0	\$278.83		
TOTAL LABOR ESTIMATE:						\$2,006.7		
EQUIPMENT TYPE			QTY	7	HOURS	AMOUN'		
0401 - Truck; 15,000 GVW; without plo	ass 0601)	1		5.0	\$44.3			
0507 - 1 Ton; Crew Cab; Diesel; 4x2		1		8.0	\$59.9			
0532 - ¾ Ton; Extended Cab; Gasoline; 4x2			1		3.0	\$17.1		
0605 - Truck; Above 38,000 GVW; 4x2; Auto Trans; Double Body; with front plow			1		5.0	\$70.2		
0820 - Truck; Flatbed; Traffic Control I GVW (Road Warrior)	n 38,000	1		5.0	\$52.5			
0825 - Truck; Flatbed; Guardrail Repair; 54,000 GVW; wi Knuckle boom Crane			1		5.0	\$52.5		
1004 - Tilt Trailer; 12,000 Lbs		1		5.0	\$5.3			
1205 - Backhoe; Excavator; Track Mounted; 30-35K Operating Weight			1		5.0	\$48.0		
TOTAL EQUIPMENT ESTIMATE:						\$350.2		

Page 1 DATE PRINTED: 1/29/2015



REPAIR COST ESTIMATE

Department of Transpor	tution		AIR COST ES			
				K1C678		
OCATION OF DAMAGE PROPERTY: COUNTY			DAMA	DAMAGE CODE		
SR 018 Begin MP: 27.90 End MP Westbound I90 RIGHT SIDE	018 Begin MP: 27.90 End MP: 27.90 Dir: 17 King stbound I90 RIGHT SIDE			31 Guardrail, Leading End		
MATERIAL TYPE			QTY	AMOUNT		
Block, Guard Rail 6x8x14"	6	\$44.53				
Bolt,Nut,Washer, 5/8x10"			1	\$2.96		
Bolt,Nut,Washer, 5/8x18"	3	\$16.05				
CRT Breakaway Post	6	\$261.12				
ET 2000 Extruder Head Terminal	1	\$895.08				
ET 2000/SRT 350 mud post for 27"	2	\$85.34				
Guard Rail, ET-2000 32G	1	\$184.44				
Guard Rail, W Beam 12' 6" Straight	4	\$436.53				
Post, Guard Rail 6"x8"x6' - Each	1	\$34.14				
Splice Bolt,Nut,Washer, 5/8x1 1/4"	40	\$97.66				
TOTAL MATERIAL ESTIMATE:				\$2,057.85		
MISCELLANEOUS CHARGES - DE	QTY	AMOUNT				
				\$0.00		
TOTAL MISCELLANEOUS ESTIMA	ATE:			\$0.00		
TOTAL CHARGES:				\$4,414.84		
MAINT. AREA LOCATION:	ORG CODE:	CONT. SECTION	JOB NO:			
Area 5 Bellevue	415510	A51018	K1C678			
SUBMITTED BY:	DATE:		•			
Donald Nelson	10/29/2013					
APPROVED BY:	DATE:	OFFICE USE ONLY:				
Jim McBride	11/04/2013	Estimate Only: Y Accident Rpt: E279913 Revised Estimate: N Work Completed: Y Work Completed Date: 10/26/2013				

Page 2 DATE PRINTED: 1/29/2015











