



REPAIR COST ESTIMATE

K1D185

LOCATION OF DAMAGE PROPERTY: SR 526 Begin MP: 3.60 End MP: 3.60 Dir: Eastbound Eastbound SR-526 right side where Evergreen Way onramp meets Eastbound SR-526 mainline.	COUNTY 31 Snohomish	DAMAGE CODE 31 Guardrail, Leading End
---	------------------------	--

DATE DAMAGE OCCURRED OR OBSERVED: 02/11/2014 OBSERVED	DESCRIPTION OF DAMAGES SKT Damage.
--	---------------------------------------

NAME AND ADDRESS OF OWNER: [REDACTED]	NAME AND ADDRESS OF DRIVER: [REDACTED]
--	---

YEAR, MAKE, TYPE OF VEHICLE: 1998 Oldsmobile Cutlass	LICENSE: A [REDACTED]	DAMAGE TAG:	POLICE DIV: Everett Police Department	BADGE: 1315
---	--------------------------	-------------	--	----------------

REPAIR COST DISTRIBUTION ESTIMATE

LABOR DESCRIPTION	QTY	REG. HOURS	O/T HOURS	AMOUNT
Maintenance Lead Tech.	1	7.0		\$361.85
Maintenance Tech. 2	4	7.0		\$1,181.75
Maintenance Tech. 3	1	7.0		\$320.11
TOTAL LABOR ESTIMATE:				\$1,863.70

EQUIPMENT TYPE	QTY	HOURS	AMOUNT
0401 - Truck; 15,000 GVW; without plow (From subclass 0601)	1	7.0	\$62.03
0606 - Truck; Above 38,000 GVW; 4x2, Contractor Body; with front plow	1	7.0	\$81.02
0820 - Truck; Flatbed; Traffic Control Items; Less Than 38,000 GVW (Road Warrior)	2	7.0	\$147.25
0825 - Truck; Flatbed; Guardrail Repair; 54,000 GVW; with Knuckle boom Crane	1	5.0	\$52.59
TOTAL EQUIPMENT ESTIMATE:			\$342.88

MATERIAL TYPE	QTY	AMOUNT
Guard Rail, Flex Beam, Straight Section 13' x 6 1/2" - Each	2	\$219.24
TOTAL MATERIAL ESTIMATE:		\$219.24



REPAIR COST ESTIMATE

K1D185

LOCATION OF DAMAGE PROPERTY: SR 526 Begin MP: 3.60 End MP: 3.60 Dir: Eastbound Eastbound SR-526 right side where Evergreen Way onramp meets Eastbound SR-526 mainline.	COUNTY 31 Snohomish	DAMAGE CODE 31 Guardrail, Leading End
---	------------------------	--

MISCELLANEOUS CHARGES - DESCRIPTION	QTY	AMOUNT
SKT End treatment Kit 5702-849-137	1.0	\$2,391.24
TOTAL MISCELLANEOUS ESTIMATE:		\$2,391.24

TOTAL CHARGES: \$4,817.07

MAINT. AREA LOCATION: Area 3 Everett	ORG CODE: 415340	CONT. SECTION A34526	JOB NO: K1D185
SUBMITTED BY: James Christo	DATE: 03/07/2014		
APPROVED BY: John Tellesbo	DATE: 03/07/2014	OFFICE USE ONLY: Estimate Only: N Accident Rpt: E305731 Revised Estimate: N Work Completed: Y Work Completed Date: 03/06/2014	









03/06/2014 00:48



03/06/2014 00:47



Date 3/7/2014		Originating Location Region MA ICP 001 03 030A			Transfer To Location (For Transfers Only) Region MA ICP			Ticket Number G35553	
<input checked="" type="checkbox"/> Issue <input type="checkbox"/> Return <input type="checkbox"/> Transfer		Work Order K1D185	Group 01	Org Code 415340	Office / Vessel / Terminal NWR Everett Maintenance				
Equip. or Cont. Sec.	Function or Work Op	Commodity Code	Description			Unit	Quantity Ordered	Quantity Iss/Ret/Trans	
A34526	3154	5702-849-137	GR COMPLETE SKT350 TL3 FOR 27 INCH TERMINAL SYSTEM NON FLARED			EA		1	
A345256	3154	5702-839-125	GR 13 FT 6 1/2 IN AT 6 FT 3 IN 12 GA GALVANIZED			EA		2	
						Terminal Entry <i>3-10-14 Jmm</i>			
Requested By Todd Jones					Authorized By				
Issued By			Received By (Legible Signature) Dave Fadden			Receiving Location			



Not to Scale

