



REPAIR COST ESTIMATE

K1D317

LOCATION OF DAMAGE PROPERTY: SR 005 Begin MP: 0.02 Dir: Northbound Westbound SR 18 Ramp to I-5 N. and S. Rightside at beginning. SR# 005 S1 14130-INC	COUNTY 17 King	DAMAGE CODE 31 Guardrail, Leading End
--	-------------------	--

DATE DAMAGE OCCURRED OR OBSERVED: 03/06/2014 OCCURRED	DESCRIPTION OF DAMAGES Guardrail and post damage. ET 2000 Type 31
--	--

NAME AND ADDRESS OF OWNER: Same [REDACTED]	NAME AND ADDRESS OF DRIVER: [REDACTED]
--	---

YEAR, MAKE, TYPE OF VEHICLE: 1999 Dodge RamChar PK	LICENSE: [REDACTED]	DAMAGE TAG:	POLICE DIV:	BADGE:
---	------------------------	-------------	-------------	--------

REPAIR COST DISTRIBUTION ESTIMATE

LABOR DESCRIPTION	QTY	REG. HOURS	O/T HOURS	AMOUNT
Maintenance Lead Tech.	1	8.0		\$379.94
Maintenance Tech. 2	1	22.0		\$871.43
Maintenance Tech. 3	1	6.0		\$261.90
TOTAL LABOR ESTIMATE:				\$1,513.27

EQUIPMENT TYPE	QTY	HOURS	AMOUNT
0414 - Truck; Flatbed; Extended Cab; Cargo; Gas	1	5.0	\$31.78
0435 - Truck; 1 Ton; with Dump Body; Extended / Crew Cab; Diesel; with Tommy Lift or Crane	1	3.0	\$31.85
0602 - Truck; Less than 38,000 GVW; with front plow	1	6.0	\$89.07
0820 - Truck; Flatbed; Traffic Control Items; Less Than 38,000 GVW (Road Warrior)	2	5.0	\$87.90
0825 - Truck; Flatbed; Guardrail Repair; 54,000 GVW; with Knuckle boom Crane	1	6.0	\$63.11
2123 - Impact Attenuator (Truck Mounted)	1	8.0	\$10.00
2160 - Message Sign; Vehicle Mounted; 3 Line Message	1	8.0	\$14.39
2303 - Sander; Tailgate	1	6.0	\$2.03
TOTAL EQUIPMENT ESTIMATE:			\$330.12



REPAIR COST ESTIMATE

K1D317

LOCATION OF DAMAGE PROPERTY: SR 005 Begin MP: 0.02 Dir: Northbound Westbound SR 18 Ramp to I-5 N. and S. Rightside at beginning. SR# 005 S1 14130-INC	COUNTY 17 King	DAMAGE CODE 31 Guardrail, Leading End
--	-------------------	--

MATERIAL TYPE	QTY	AMOUNT
GUARDRAIL, BLOCK SPACER 6X12X14 - 5421-011-015	3	\$47.35
GUARDRAIL, BOLT NUT WASHER 5/8 X 1 1/4	24	\$28.77
GUARDRAIL, BOLT NUT WASHER 5/8 X 10"	2	\$4.14
GUARDRAIL, ET 2000 PANEL 1 - 5421-010-500	1	\$184.20
GUARDRAIL, ET 2000 TYPE 31 PANEL - 5421-010-510	1	\$91.55
GUARDRAIL, SRT 350 DRILLED POST 6X8X6 CRT - 5421-052-350	3	\$223.75
POST, GUARDRAIL 6X8X4' 1/4" ANCHOR - ET TYPE 31 - 5421-052-425	2	\$64.39
TOTAL MATERIAL ESTIMATE:		\$644.15

MISCELLANEOUS CHARGES - DESCRIPTION	QTY	AMOUNT
		\$0.00
TOTAL MISCELLANEOUS ESTIMATE:		\$0.00

TOTAL CHARGES: \$2,487.54

MAINT. AREA LOCATION: KELLEHP@wsdot.wa.gov	ORG CODE: 415420	CONT. SECTION A42005	JOB NO: K1D317
SUBMITTED BY: John Sipp	DATE: 04/15/2014		
APPROVED BY: Tom Wagner	DATE: 04/15/2014	OFFICE USE ONLY: Estimate Only: Y Accident Rpt: E312262 Revised Estimate: N Work Completed: Y Work Completed Date: 03/18/2014	



03.06.2014 08:12



03.06.2014 08:12



03.06.2014 08:13



03.06.2014 09:38



03.18.2014 08:03



03.18.2014 08:03



03.18.2014 08:04



TRIPLICATE

Stores Issue

8420

<input checked="" type="checkbox"/> I - Issue <input type="checkbox"/> R - Return <input type="checkbox"/> T - Transfer		Date (Mo/Da/Yr) 3/18/14	Originating Location Region: NW Div: 4 ICP: 040			Issue Ticket No. A 75307		
Transfer to Location Region: Div: ICP:		Work Order KID317		Group 01	Object		Org Code 415420	
Equip. or Cont. Sec.	Work Op	Stock Number	Description			Unit	Quantity Ordered	Quantity Issued
A42005	3154	570-28-49-521	ET2000 #1 Rail			ea		1
		570-28-49-524	ET 2000 TYPE 31 # 2 Rail			ea		1
		540-73-41-300	ET 2000 TYPE 31 Post 6x8x4.25			ea		2
		540-73-35-282	GR BLOCK TYPE 31 6x8x14			ea		3
		540-73-41-250	POST, GR CRT			ea		2
Authorization		Issued By Charles A. Edwards <i>[Signature]</i>		Received By <i>[Signature]</i>		Receiving Location		