



## REPAIR COST ESTIMATE

K1D474

LOCATION OF DAMAGE PROPERTY: SR 405 Begin MP: 25.42 Dir: Northbound Right side south of SR-527		COUNTY 31 Snohomish	DAMAGE CODE 31 Guardrail, Leading End	
DATE DAMAGE OCCURRED OR OBSERVED: 04/11/2014 OCCURRED		DESCRIPTION OF DAMAGES END TREATMENT		
NAME AND ADDRESS OF OWNER: [REDACTED]		NAME AND ADDRESS OF DRIVER: [REDACTED]		
YEAR, MAKE, TYPE OF VEHICLE: 1998 Subaru Legacy	LICENSE: [REDACTED]	DAMAGE TAG:	POLICE DIV: Washington State Patrol	BADGE: 1141

### REPAIR COST DISTRIBUTION ESTIMATE

LABOR DESCRIPTION	QTY	REG. HOURS	O/T HOURS	AMOUNT
Maintenance Lead Tech.	1	4.0		\$201.02
Maintenance Tech. 2	6	4.0		\$953.36
<b>TOTAL LABOR ESTIMATE:</b>				<b>\$1,154.38</b>

EQUIPMENT TYPE	QTY	HOURS	AMOUNT
0533 - ¾ Ton; Extended Cab; Diesel; 4x2	1	4.0	\$26.24
0606 - Truck; Above 38,000 GVW; 4x2, Contractor Body; with front plow	1	4.0	\$46.29
0820 - Truck; Flatbed; Traffic Control Items; Less Than 38,000 GVW (Road Warrior)	1	4.0	\$42.07
0825 - Truck; Flatbed; Guardrail Repair; 54,000 GVW; with Knuckle boom Crane	1	4.0	\$42.07
2123 - Impact Attenuator (Truck Mounted)	1	4.0	\$4.80
2303 - Sander; Tailgate	1	4.0	\$1.35
<b>TOTAL EQUIPMENT ESTIMATE:</b>			<b>\$162.82</b>

MATERIAL TYPE	QTY	AMOUNT
CRT Breakaway Post	3	\$130.56
ET 2000 Type 31 mud post	2	\$63.15
ET2000 Type 31 rail 15' 7"	1	\$213.44
Guard Rail, ET-2000 32G	1	\$184.29
Guardrail, Type 31	1	\$144.11
<b>TOTAL MATERIAL ESTIMATE:</b>		<b>\$735.54</b>



**REPAIR COST ESTIMATE**

**K1D474**

LOCATION OF DAMAGE PROPERTY: SR 405 Begin MP: 25.42 Dir: Northbound Right side south of SR-527	COUNTY 31 Snohomish	DAMAGE CODE 31 Guardrail, Leading End
--	------------------------	--

MISCELLANEOUS CHARGES - DESCRIPTION	QTY	AMOUNT
misc	1.0	\$98.58
<b>TOTAL MISCELLANEOUS ESTIMATE:</b>		<b>\$98.58</b>

**TOTAL CHARGES: \$2,151.32**

MAINT. AREA LOCATION: Area 5 Bellevue	ORG CODE: 415530	CONT. SECTION A53405	JOB NO: K1D474
SUBMITTED BY: Tony Virello	DATE: 05/12/2014		
APPROVED BY: Jim McBride	DATE: 05/14/2014	OFFICE USE ONLY: Estimate Only: N Accident Rpt: E321186 Revised Estimate: N Work Completed: Y Work Completed Date: 04/14/2014	









TRINITY 00  
CIA 060  
00/2017

