# Washington State Department of Transportation

#### **REPAIR COST ESTIMATE**

					K1D902			
LOCATION OF DAMAGE PROPERTY	:		COUNTY	DAMA	DAMAGE CODE			
SR 002 Begin MP: 3.80 Dir: Eastbou E/B at Bickford Exit on the Left.	IND US 2 MP 3.	8 31	Snohomish	31 Guardra	31 Guardrail, Leading End			
DATE DAMAGE OCCURRED OR OB	SERVED:	DESC	RIPTION OF D	DAMAGES				
08/08/2014	OCCURRED	SKT G	-Rail End and	Exit Sign on steel p	ost slip base.			
NAME AND ADDRESS OF OWNER:		NAME	AND ADDRES	SS OF DRIVER:				
YEAR, MAKE, TYPE OF VEHICLE:	LICENSE:	DAMA	GE TAG: PO	DLICE DIV:	BADGE:			
2008 Chev HHR	4		Wa	ashington State Patr	ol 691			
F	REPAIR COST D	ISTRIBUT	ION ESTIMA	TE				
LABOR DESCRIPTION		QTY	REG. HOU	RS O/T HOURS	AMOUNT			
Maintenance Lead Tech.		1	2.0	0.0	\$103.89			
Maintenance Lead Tech.		1	2.0		\$103.89			
Maintenance Specialist 3		1	2.0		\$101.77			
Maintenance Supervisor		1	2.0	0.0	\$112.90			
Maintenance Tech. 2		3	5.0		\$636.16			
Maintenance Tech. 3		1	5.0		\$229.76			
TOTAL LABOR ESTIMATE:					\$1,288.37			
EQUIPMENT TYPE			QTY	HOURS	AMOUNT			
0305 - Truck; Pickup; Incident Respons	se (IRL); Diesel		1	2.0	\$24.80			
0435 - Truck; 1 Ton; with Dump Body; Diesel; with Tommy Lift or Crane	Extended / Crew	Cab;	1	2.0	\$21.53			
0505 - 1 Ton; Crew Cab; Gasoline; 4x2	2		1	2.0	\$12.55			
0533 - ¾ Ton; Extended Cab; Diesel; 4	x2		1	2.0	\$12.95			
0820 - Truck; Flatbed; Traffic Control It GVW (Road Warrior)	ems; Less Than	38,000	1	5.0	\$51.36			
0825 - Truck; Flatbed; Guardrail Repai Knuckle boom Crane	r; 54,000 GVW; v	with	1	7.0	\$71.14			
TOTAL EQUIPMENT ESTIMATE:					\$194.33			
MATERIAL TYPE				QTY	AMOUNT			
Post, Sign, Perforated, 2 1/2 In x 2 1/2	In x 14 Feet - Ea	ach		1	\$73.97			
Slip Base Hardware Kit	1	\$23.92						
TOTAL MATERIAL ESTIMATE:				I	\$97.89			

Washington State Department of Transportation

#### **REPAIR COST ESTIMATE**

Department of transporta							
				K1D902			
LOCATION OF DAMAGE PROPERTY:	:	COUNTY	DAM	AGE CODE			
SR 002 Begin MP: 3.80 Dir: Eastbou E/B at Bickford Exit on the Left.	IND US 2 MP 3.8	31 Snohomish	31 Guard	rail, Leading End			
MISCELLANEOUS CHARGES - DESC	QTY	AMOUNT					
SKT Type 31 Kit		1.0	\$3,054.20				
TOTAL MISCELLANEOUS ESTIMATE	Ξ:			\$3,054.20			
TOTAL CHARGES:				\$4,634.79			
MAINT. AREA LOCATION:	ORG CODE:	CONT. SECTION	JOB NO:				
Area 3 Everett	415340	A34002	K1D902				
SUBMITTED BY:	DATE:						
Todd Jones	08/21/2014						
APPROVED BY:	DATE:	OFFICE USE ONLY:					
John Tellesbo	08/21/2014	Estimate Only: N Acc Revised Estimate: N Work Completed: Y Work Completed Date: 0	ident Rpt: E348 08/27/2014	817			











## Stores Ticket (8420)

Date			Originating Loca Region								Ticke	t Number		
8/11	/2014		001	03		030A						<b>G37</b>	464	
		Wo	ork Order	Group	)	Org Code		Offi	ce / Vessel /	Terminal				
□ Return □ Transfer K1D902				0	1 415340 NWR Everett Maintenance						e	k.		
Equip. or Cont. Sec.	Function Work C		Commodity	modity Code				Description					Quar Iss/Ret/	
A34002	3131	31 + 80 + 3 - 048 - 707					T TELESPAR 2 1/2 X 2 1/2 IN X 14 FT 12 AGE GALVANIZED							1
							2			<u>е</u>		÷		
											S.			
				3						Tern	ninal	Entry	8-12-1	49m
														6
Requested I	Ву						Author	ized E	Зу					
						8	Sage	e Joi	nes					
Issued By					Rece	eived By (Legib	le Signature	e)		Receiving L	ocation			
					See	e issue tick	et			8 - C				
DOT Form 72 Revised	25-015 EF 8/08						File Copy		т. т.					









### **Stores Ticket (8420)**

Date			Originating Loca	tion			Transfer T	o Loo	cation (For Tran	nsfers Only)	Ticke	t Number	
L Complex			Region	MA	.	ICP	Regior	ı	MA	ICP			
8/28	8/2014		001	03		030A				8		<b>G37</b>	658
🛛 Issue		Wo	ork Order	Group	C	Org Code		Offi	ice / Vessel /	Terminal			
Retur	TIADOOO				1	415340 NWR Everett Maintenanc							
Equip. or Cont. Sec.	Function Work C	Commodity Code				Description						Quantity Ordered	Quantity Iss/Ret/Trans
A34002	3154		5702-849-:	565	SKT 350, TYPE 31,40'7-1/2",STEEL POST, POLY BLOCK, Non-flared Terminal System								1
ar.									~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~				
										Terminal	Entry	8-27-1	4 gmm
4											а		, ,
													i a
Requested E	Зу			8			Authori	zed E	Ву		1		
Todd W	Jones												
Issued By					Rece	eived By (Legib	le Signature	)		Receiving L	ocation		
					Eri	c Mills		•		Everett			
OOT Form 72													

DOT Form 725-015 EF Revised 8/08