



REPAIR COST ESTIMATE

K1B277

LOCATION OF DAMAGE PROPERTY: SR 532 Begin MP: 8.58 Dir: Eastbound EB direction on SR 532. MP 8.58		COUNTY 31 Snohomish	DAMAGE CODE 31 Guardrail, Leading End	
DATE DAMAGE OCCURRED OR OBSERVED: 10/28/2012 OBSERVED		DESCRIPTION OF DAMAGES Damage to Guardrail end.		
NAME AND ADDRESS OF OWNER: Same Same		NAME AND ADDRESS OF DRIVER: [REDACTED]		
YEAR, MAKE, TYPE OF VEHICLE: 2004 Honda Accord	LICENSE: [REDACTED]	DAMAGE TAG:	POLICE DIV: Washington State Patrol	BADGE: 310

REPAIR COST DISTRIBUTION ESTIMATE

LABOR DESCRIPTION	QTY	REG. HOURS	O/T HOURS	AMOUNT
Maintenance Lead Tech.	1	8.0	0.0	\$383.06
Maintenance Tech. 2	1	7.0	0.0	\$274.14
Maintenance Tech. 2	1	8.0	0.0	\$313.31
Maintenance Tech. 2	1	8.0	0.0	\$313.31
Maintenance Tech. 2	1	6.0	0.0	\$234.98
Maintenance Tech. 2	1	6.0	0.0	\$234.98
TOTAL LABOR ESTIMATE:				\$1,753.77

EQUIPMENT TYPE	QTY	HOURS	AMOUNT
0433 - Truck; 1 Ton; with Dump Body; Extended / Crew Cab; Diesel	1	6.0	\$43.98
0507 - 1 Ton; Crew Cab; Diesel; 4x2	1	8.0	\$68.42
0820 - Truck; Flatbed; Traffic Control Items; Less Than 38,000 GVW (Road Warrior)	1	8.0	\$83.17
0825 - Truck; Flatbed; Guardrail Repair; 54,000 GVW; with Knuckle boom Crane	1	8.0	\$94.28
2123 - Impact Attenuator (Truck Mounted)	1	8.0	\$9.60
2160 - Message Sign; Vehicle Mounted; 3 Line Message	1	8.0	\$15.28
TOTAL EQUIPMENT ESTIMATE:			\$314.73



REPAIR COST ESTIMATE

K1B277

LOCATION OF DAMAGE PROPERTY: SR 532 Begin MP: 8.58 Dir: Eastbound EB direction on SR 532. MP 8.58	COUNTY 31 Snohomish	DAMAGE CODE 31 Guardrail, Leading End
---	------------------------	--

MATERIAL TYPE	QTY	AMOUNT
Guard Rail - Wood Block, Spacer 6x8x14"	4	\$34.83
Guard Rail - Wood Post, 6" x 8" x 4.25'	2	\$73.86
Guard Rail ET2000 Panel 1, SYRO	1	\$184.32
Guard Rail, Beam, Punched Type 31	2	\$290.20
Guard Rail, ET Extruder Head Terminal	1	\$901.31
Guard Rail, Post, 10x10x7 Special Thrie Beam	1	\$23.36
Guard Rail, Post, 6" x 8" x 6', CRT. 2-Hole	4	\$182.24
TOTAL MATERIAL ESTIMATE:		\$1,690.13

MISCELLANEOUS CHARGES - DESCRIPTION	QTY	AMOUNT
		\$0.00
TOTAL MISCELLANEOUS ESTIMATE:		\$0.00

TOTAL CHARGES: \$3,758.63

MAINT. AREA LOCATION: Area 2 Mt Vernon	ORG CODE: 415220	CONT. SECTION A22532	JOB NO: K1B277
SUBMITTED BY: John Tate	DATE: 04/16/2013		
APPROVED BY: Kim Glass	DATE: 04/16/2013	OFFICE USE ONLY: Estimate Only: Y Accident Rpt: E203493 Revised Estimate: N Work Completed: Y Work Completed Date: 10/30/2012	

BU
WASHINGTON

ACR9381

GREEN STATE
7SHO COM





PERMITS ONLY
SMILE VIEW ESTATES