



## REPAIR COST ESTIMATE

K1D075

|   |                   |  |
|---|-------------------|--|
| LOCATION OF DAMAGE PROPERTY:<br>SR 599 Begin MP: 0.33 Dir: Northbound NB SR599<br>left side just S of 133rd.ST, Tukwila | COUNTY<br>17 King | DAMAGE CODE<br>31 Guardrail, Leading End |
|---|-------------------|--|

|  |   |
|--|---|
| DATE DAMAGE OCCURRED OR OBSERVED:<br>01/08/2014 OCCURRED | DESCRIPTION OF DAMAGES<br>guardrail leading end |
|--|---|

|  |   |
|--|---|
| NAME AND ADDRESS OF OWNER:<br>Same<br>[REDACTED] | NAME AND ADDRESS OF DRIVER:<br>[REDACTED] |
|--|---|

|   |                          |             |  |                |
|---|--------------------------|-------------|--|----------------|
| YEAR, MAKE, TYPE OF VEHICLE:<br>2000 Chevrolet S10 Pickup | LICENSE:<br>B [REDACTED] | DAMAGE TAG: | POLICE DIV:<br>Washington State Patrol | BADGE:<br>1072 |
|---|--------------------------|-------------|--|----------------|

### REPAIR COST DISTRIBUTION ESTIMATE

| LABOR DESCRIPTION            | QTY | REG. HOURS | O/T HOURS | AMOUNT            |
|------------------------------|-----|------------|-----------|-------------------|
| Maintenance Lead Tech.       | 2   |            | 3.0       | \$386.44          |
| Maintenance Supervisor       | 1   |            | 3.0       | \$222.89          |
| Maintenance Tech. 2          | 5   |            | 3.0       | \$796.12          |
| Maintenance Tech. 3          | 1   |            | 3.0       | \$167.30          |
| <b>TOTAL LABOR ESTIMATE:</b> |     |            |           | <b>\$1,572.75</b> |

| EQUIPMENT TYPE  | QTY | HOURS | AMOUNT          |
|---|-----|-------|-----------------|
| 0432 - Truck; 1 Ton; with Dump Body; Extended / Crew Cab; Gas                     | 1   | 3.0   | \$25.01         |
| 0532 - ¾ Ton; Extended Cab; Gasoline; 4x2   | 1   | 3.0   | \$17.13         |
| 0602 - Truck; Less than 38,000 GVW; with front plow                               | 1   | 3.0   | \$44.53         |
| 0810 - Truck; Attenuator Rent charged for operating costs only                    | 1   | 3.0   | \$18.21         |
| 0820 - Truck; Flatbed; Traffic Control Items; Less Than 38,000 GVW (Road Warrior) | 2   | 3.0   | \$63.11         |
| 0825 - Truck; Flatbed; Guardrail Repair; 54,000 GVW; with Knuckle boom Crane      | 1   | 3.0   | \$31.55         |
| <b>TOTAL EQUIPMENT ESTIMATE:</b>  |     |       | <b>\$199.55</b> |

| MATERIAL TYPE                         | QTY | AMOUNT          |
|---------------------------------------|-----|-----------------|
| ET 2000/SRT 350 mud post for 27" rail | 2   | \$85.34         |
| Guard Rail, ET-2000 32G               | 1   | \$184.44        |
| Post, Guard Rail 6"x8"x6' - Each      | 1   | \$34.14         |
| <b>TOTAL MATERIAL ESTIMATE:</b>       |     | <b>\$303.92</b> |



**REPAIR COST ESTIMATE**

**K1D075**

|   |                   |  |
|---|-------------------|--|
| LOCATION OF DAMAGE PROPERTY:<br>SR 599 Begin MP: 0.33 Dir: Northbound NB SR599<br>left side just S of 133rd.ST, Tukwila | COUNTY<br>17 King | DAMAGE CODE<br>31 Guardrail, Leading End |
|---|-------------------|--|

| MISCELLANEOUS CHARGES - DESCRIPTION  | QTY | AMOUNT        |
|--------------------------------------|-----|---------------|
|                                      |     | \$0.00        |
| <b>TOTAL MISCELLANEOUS ESTIMATE:</b> |     | <b>\$0.00</b> |

**TOTAL CHARGES: \$2,076.22**

|  |                     |   |                   |
|--|---------------------|---|-------------------|
| MAINT. AREA LOCATION:<br>Area 5 Bellevue | ORG CODE:<br>415520 | CONT. SECTION<br>A52599   | JOB NO:<br>K1D075 |
| SUBMITTED BY:<br>Scott Read              | DATE:<br>02/21/2014 |   |                   |
| APPROVED BY:<br>Jim McBride              | DATE:<br>02/26/2014 | OFFICE USE ONLY:<br>Estimate Only: Y Accident Rpt: E298837<br>Revised Estimate: N<br>Work Completed: Y<br>Work Completed Date: 02/08/2014 |                   |



