



## REPAIR COST ESTIMATE

K1D257

LOCATION OF DAMAGE PROPERTY: SR 599 Begin MP: 0.10 Dir: Northbound NB- SR-599 Right side just south of Interurban Ave, Tukwila		COUNTY 17 King	DAMAGE CODE 31 Guardrail, Leading End		
DATE DAMAGE OCCURRED OR OBSERVED: 02/04/2014 OCCURRED		DESCRIPTION OF DAMAGES guardrail leading end			
NAME AND ADDRESS OF OWNER:		NAME AND ADDRESS OF DRIVER: [REDACTED]			
YEAR, MAKE, TYPE OF VEHICLE:	LICENSE:	DAMAGE TAG: 006481	POLICE DIV: Washington State Patrol	BADGE: 1240	
REPAIR COST DISTRIBUTION ESTIMATE					
LABOR DESCRIPTION	QTY	REG. HOURS	O/T HOURS	AMOUNT	
Maintenance Lead Tech.	1	4.0		\$206.77	
Maintenance Tech. 2	3	4.0		\$530.58	
Maintenance Trainee	1	4.0		\$133.40	
<b>TOTAL LABOR ESTIMATE:</b>				<b>\$870.75</b>	
EQUIPMENT TYPE	QTY	HOURS		AMOUNT	
0433 - Truck; 1 Ton; with Dump Body; Extended / Crew Cab; Diesel	1	4.0		\$29.65	
0532 - ¾ Ton; Extended Cab; Gasoline; 4x2	1	4.0		\$22.84	
0602 - Truck; Less than 38,000 GVW; with front plow	1	4.0		\$59.38	
0825 - Truck; Flatbed; Guardrail Repair; 54,000 GVW; with Knuckle boom Crane	1	4.0		\$42.07	
<b>TOTAL EQUIPMENT ESTIMATE:</b>				<b>\$153.94</b>	
MATERIAL TYPE	QTY		AMOUNT		
ET 2000 Type 31 mud post	1		\$31.57		
Guard Rail, ET-2000 32G	1		\$184.44		
<b>TOTAL MATERIAL ESTIMATE:</b>				<b>\$216.02</b>	



**REPAIR COST ESTIMATE**

**K1D257**

LOCATION OF DAMAGE PROPERTY: SR 599 Begin MP: 0.10 Dir: Northbound NB- SR-599 Right side just south of Interurban Ave, Tukwila	COUNTY 17 King	DAMAGE CODE 31 Guardrail, Leading End
--	-------------------	--

MISCELLANEOUS CHARGES - DESCRIPTION	QTY	AMOUNT
		\$0.00
<b>TOTAL MISCELLANEOUS ESTIMATE:</b>		<b>\$0.00</b>

**TOTAL CHARGES: \$1,240.71**

MAINT. AREA LOCATION: Area 5 Bellevue	ORG CODE: 415520	CONT. SECTION A52599	JOB NO: K1D257
SUBMITTED BY: Scott Read	DATE: 03/12/2014		
APPROVED BY: Tom Wagner	DATE: 03/12/2014	OFFICE USE ONLY: Estimate Only: N Accident Rpt: E308147 Revised Estimate: N Work Completed: Y Work Completed Date: 02/27/2014	







