



## REPAIR COST ESTIMATE

K1D920

LOCATION OF DAMAGE PROPERTY: SR 203 Begin MP: 10.00 End MP: 10.00 Dir: Southbound S/B 203	COUNTY 17 King	DAMAGE CODE 31 Guardrail, Leading End
---	-------------------	--

DATE DAMAGE OCCURRED OR OBSERVED: 08/15/2014 OBSERVED	DESCRIPTION OF DAMAGES Guardrail damage Leading End
--	--

NAME AND ADDRESS OF OWNER: [REDACTED]	NAME AND ADDRESS OF DRIVER: Billy Thomason [REDACTED]
--	---

YEAR, MAKE, TYPE OF VEHICLE: 2005 Peterbilt Tractor	LICENSE: [REDACTED]	DAMAGE TAG:	POLICE DIV: Washington State Patrol	BADGE: 1153
--	------------------------	-------------	--	----------------

### REPAIR COST DISTRIBUTION ESTIMATE

LABOR DESCRIPTION	QTY	REG. HOURS	O/T HOURS	AMOUNT
Maintenance Lead Tech.	1	2.0		\$103.89
Maintenance Tech. 2	4	5.9		\$1,000.89
Maintenance Tech. 3	1	6.0		\$275.71
Maintenance Tech. 3	1	3.0	3.0	\$305.97
<b>TOTAL LABOR ESTIMATE:</b>				<b>\$1,686.46</b>

EQUIPMENT TYPE	QTY	HOURS	AMOUNT
0415 - Truck; Flatbed; Extended Cab; Cargo; Diesel	1	5.0	\$36.09
0437 - Truck; 1 Ton; with Dump Body; Regular Cab; Diesel	1	8.0	\$38.29
0515 - ¼ Ton; Crew Cab; 4x4	1	2.0	\$8.91
0825 - Truck; Flatbed; Guardrail Repair; 54,000 GVW; with Knuckle boom Crane	1	5.0	\$50.82
<b>TOTAL EQUIPMENT ESTIMATE:</b>			<b>\$134.11</b>

MATERIAL TYPE	QTY	AMOUNT
Block, Guard Rail, King Block - Each	1	\$17.27
ET 2000 Extruder Head Terminal	1	\$899.35
Guard Rail ET 2000 # 1	1	\$183.13
Guard Rail, 13' 6 1/2" 3' 1 1/2" Type 31	2	\$286.15
Post, Guard Rail 6"x8"x 3' 9"	2	\$86.10
Post, Guard Rail, 6" x 8" x 6' CRT 2 hole	1	\$45.18
<b>TOTAL MATERIAL ESTIMATE:</b>		<b>\$1,517.18</b>



**REPAIR COST ESTIMATE**

**K1D920**

LOCATION OF DAMAGE PROPERTY: SR 203 Begin MP: 10.00 End MP: 10.00 Dir: Southbound S/B 203	COUNTY 17 King	DAMAGE CODE 31 Guardrail, Leading End
---	-------------------	--

MISCELLANEOUS CHARGES - DESCRIPTION	QTY	AMOUNT
		\$0.00
<b>TOTAL MISCELLANEOUS ESTIMATE:</b>		<b>\$0.00</b>

**TOTAL CHARGES: \$3,337.75**

MAINT. AREA LOCATION: Area 3, Monroe	ORG CODE: 415320	CONT. SECTION a32203	JOB NO: K1D920
SUBMITTED BY: Edward Gasca	DATE: 08/26/2014		
APPROVED BY: John Tellesbo	DATE: 08/26/2014	OFFICE USE ONLY: Estimate Only: Y Accident Rpt: E349320 Revised Estimate: N Work Completed: Y Work Completed Date: 08/20/2014	





08/20/2014





Washington State  
Department of Transportation

# Stores Ticket (8420)

Date 8/25/14		Originating Location Region 1 MA 3 ICP 033A			Transfer To Location (For Transfers Only) Region MA ICP			Ticket Number A 13769	
<input checked="" type="checkbox"/> Issue <input type="checkbox"/> Return <input type="checkbox"/> Transfer		Work Order K10920	Group 01	Org Code 415320	Office / Vessel / Terminal				
Equip. or Cont. Sec.	Function or Work Op	Commodity Code	Description			Unit	Quantity Ordered	Quantity Iss/Ret/Trans	
A32203	3154	5702 839 124	Reg Rail Type 3 1			EA		2	
A32203	3154	5702-849-521	Et2000 Panel #1			EA		1	
A32203	3154	5702 849-265	Et2000 Extender Head Terminal			EA		1	
A32203	3154	5407-341-202	Post 6x8x6 <sup>ft</sup> ert 2 Hole			EA		1	
A32203	3154	5407-335-202	Wood Block 6x12x14 (King)			EA		1	
Requested By John Lockman					Authorized By <i>[Signature]</i> Terminal Entry 9-4-14 <i>[Signature]</i>				
Issued By Ed Busca			Received By (Legible Signature) John Lockman			Receiving Location Monroe			



Washington State  
Department of Transportation

# Stores Ticket (8420)

Date 8/25/14		Originating Location Region 1 MA 3 ICP 033A			Transfer To Location (For Transfers Only) Region MA ICP			Ticket Number A 13770	
<input checked="" type="checkbox"/> Issue <input type="checkbox"/> Return <input type="checkbox"/> Transfer		Work Order K10920	Group 01	Org Code 415320	Office / Vessel / Terminal				
Equip. or Cont. Sec.	Function or Work Op	Commodity Code	Description			Unit	Quantity Ordered	Quantity Iss/Ret/Trans	
A32203	3154	5407-341-175	6in x 8in 3FT 9in Wood Break away			EA		2	
					Terminal Entry 9-4-14 <i>[Signature]</i>				
Requested By John Lockman					Authorized By <i>[Signature]</i>				
Issued By Ed Busca			Received By (Legible Signature) John Lockman			Receiving Location Monroe			